

Select Instructions

Extra Parts Bag for Single & Two Stage Gas Furnaces

EXTRA PARTS BAG FOR *G7 / *GC2 (SC, SL, SM, TL) FURNACES - P/N M0001112		
PART NUMBER	DESCRIPTION	QUANTITY
600364	#10, 1-1/4" Inducer Screw	1
606286	Hose Clamp	2
631758	Strain Relief Bushing	1
632261	3 Amp Fuse	1
663894	1/2" x 3/8" Barb Reducer	1
663989	1/2" Barb x 3/4" NPTF Connector	1
664434	23" Drain Tube	1
664633	Inlet Air Finish Flange	1
689089	7/8" ID Gas Line Grommet	1
690074	2-1/4" ID Vent Grommet	1
690094	3/4" ID Condensate Grommet	1
690101	3-1/2" OD Finish Flange Gasket	1

Table 1. Extra Parts Bag Contents - M0001112

EXTRA PARTS BAG FOR *G7 / *GC2 (SD, TC, MQ) FURNACES - P/N M0001113		
PART NUMBER	DESCRIPTION	QUANTITY
600364	#10, 1-1/4" Inducer Screw	1
606286	Hose Clamp	2
631758	Strain Relief Bushing	1
632261	3 Amp Fuse	1
663115	2" PVC Tee	1
663894	1/2" x 3/8" Barb Reducer	1
663989	1/2" Barb x 3/4" NPTF Connector	1
664434	23" Drain Tube	1
664633	Inlet Air Finish Flange	1
664659	PVC Trap	1
689089	7/8" ID Gas Line Grommet	1
690074	2-1/4" ID Vent Grommet	1
690094	3/4" ID Condensate Grommet	1
690101	3-1/2" OD Finish Flange Gasket	1

Table 2. Extra Parts Bag Contents - M0001113




Figure 1. Inline Drain Assembly Diagram

NOTES:

It is necessary to vent this furnace according to the methods described in the Venting Requirement section of the furnace installation instructions. Please refer to the installation instructions for proper usage of the listed parts.

Before permanently installing these components, it is recommended you dry-fit them first to ensure proper fit and alignment with other vent pipes.

NORDYNE
COMPLETE COMFORT. GENUINE VALUE.

Specifications & illustrations subject to change without notice or incurring obligations.
O' Fallon, MO | Printed in U.S.A. (11/11)



709136C (Replaces 709136B)