


WIRING DIAGRAM

GHH24(7.0)FMK4DH-1



WARNING

Please don't touch any electronic component or terminal when the machine is running, stopping or has been powered off for less than 30 minutes to prevent electric shock!



600007066388

958F-0923